

## ELSO Registry Change Log – April 15, 2026

1. New data structure: Hospitalizations
2. New device type: Console devices
3. Complication failure location change: Complication failure inside Equipment ML and BP sections.
4. ICD 10 wizard picker change: Allow custom ICD 10 code pick when user selects "PHTN due other cause" and "HRF due to other cause" from wizard picker options.
5. XML Import structure change: MembraneLungs/Pumps/Consoles structure change in XML import
6. Transfer Out and Back to center
7. Duration Complications
8. Duration beyond run hours increased from 168 (7 days) to 336 (14 days) for complication codes 901, 903 and 904
9. Complication Circuit Change new validation requiring device replacement
10. Extubated lookup list updated
11. Vent Validations updated
12. Discharged on ECMO logic changes
13. Cannulations Unknown Cannula